# Summary of 19 Notices of Violation Issued to Republic Airways Holdings

FAA Corporate Name	Docket Number	PWS Number	FAA Registry	Violations included in NOV that need to be addressed
Chautauqua Airlines, Inc.	1300020	AC0001964	N285SK	These two aircraft have a Treatment Technique violation for failure to perform corrective action in response to a total Coliform positive sample.
	1300021	AC0001972	N272SK	
Frontier Airlines, Inc.	1300022	AC0002100	N938FR	These two aircraft have a Treatment Technique violation for failure to perform corrective action in response to a total Coliform positive sample.
	1300023	AC0002120	N204FR	
Republic Airlines, Inc.	1300019	AC0001860	N34NG	This aircraft has a Treatment Technique violation for failure to perform corrective action in response to a total Coliform positive sample.
	1300016	AC0001840	N188WQ	Each of these 8 aircraft has the following two violations:
	1300018	AC0001859	N339NG	(1) Monitoring Violation for failure to collect annual Routine Coliform Sample for 2012; and  (2)Treatment Technique violation for failure to perform corrective Disinfection and Flushing, and taking Follow-up samples as a result of the failure to collect the annual routine Coliform samples in 2012.
	1300024	AC0002243	N127HQ	
	1300025	AC0002249	N133HQ	
	1300027	AC0002258	N164HQ	
	1300028	AC0002282	N813MA	
	1300029	AC0002288	N819MD	
	1300030	AC0002297	N829MD	
	1300031	AC0002261	N167HQ	Each of these 2 aircraft has the following four violations:  (1) Monitoring Violation for failure to collect annual Routine Coliform Sample for 2012;  (2) Treatment Technique violation for failure to perform corrective Disinfection and Flushing (D&F), and taking Follow-up samples as a result of the failure to collect the annual routine Coliform samples in 2012;  (3) Treatment Technique violation for failure to perform third quarter 2012 routine D&F and  (4) Treatment Technique violation for failure to perform corrective D&F, and taking Follow-up samples as a result of the failure to perform routine D&F for third quarter 2012.
	1300032	AC0005511	N502LX	
	1300017	AC0001854	N328NG	Each of these 3 aircraft has the following two violations:  (1) Treatment Technique violation for failure to perform third quarter 2012 routine Disinfection and Flushing (D&F); and (2) Treatment Technique violation for failure to perform corrective D&F, and taking Follow-up samples as a result of the failure to perform routine D&F for third quarter 2012.
	1300026	AC0002257	N163HQ	
	1300035	AC0002259	N165HQ	
	1300014	AC0001839	N187WQ	This aircraft has the following two violations:  (1) Treatment Technique violation for failure to perform fourth quarter 2012 routine D&F and  (2) Treatment Technique violation for failure to perform corrective D&F, and taking Follow-up samples as a result of the failure to perform routine D&F for fourth quarter 2012.

Chautauqua Airlines, Inc.

Aircraft Public Water System Identification Number: AC0001964

FAA Registry Number: N285SK

Docket Number: 1300020

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format. Pursuant to 40 C.F.R. § 141.806, Chautauqua Airlines, Inc. must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.

Based on EPA's review of ARCS, Chautauqua Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0001964:

Complete and report the corrective actions required in response to a total coliform-positive sample. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). If any routine sample is total coliform-positive and *E.coli*-negative, the air carrier must perform corrective actions under 40 C.F.R. § 141.803(c)(3). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine D&F, or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Chautauqua Airlines, Inc.

Aircraft Public Water System Identification Number: AC0001972

FAA Registry Number: N272SK

Docket Number: 1300021

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format. Pursuant to 40 C.F.R. § 141.806, Chautauqua Airlines, Inc. must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.

Based on EPA's review of ARCS, Chautauqua Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0001972:

Complete and report the corrective actions required in response to a total coliform-positive sample. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). If any routine sample is total coliform-positive and *E.coli*-negative, the air carrier must perform corrective actions under 40 C.F.R. § 141.803(c)(3). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine D&F, or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Frontier Airlines, Inc.

Aircraft Public Water System Identification Number: AC0002100

FAA Registry Number: N938FR

Docket Number: 1300022

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format. Pursuant to 40 C.F.R. § 141.806, Frontier Airlines, Inc. must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.

Based on EPA's review of ARCS, Frontier Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0002100:

Complete and report the corrective actions required in response to a total coliformpositive sample. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d).

If any routine sample is total coliform-positive and *E.coli*-negative, the air carrier must
perform corrective actions under 40 C.F.R § 141.803(c)(3). Pursuant to 40 C.F.R.
§ 141.806, air carriers must report to the EPA all events requiring notification to
passengers or crew, or non-routine D&F, or non-routine sampling within 10 days of the
event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Frontier Airlines, Inc.

Aircraft Public Water System Identification Number: AC0002120

FAA Registry Number: N204FR

Docket Number: 1300023

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format. Pursuant to 40 C.F.R. § 141.806, Frontier Airlines, Inc. must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.

Based on EPA's review of ARCS, Frontier Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0002120:

Complete and report the corrective actions required in response to a total coliform-positive sample. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). If any routine sample is total coliform-positive and *E.coli*-negative, the air carrier must perform corrective actions under 40 C.F.R § 141.803(c)(3). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine D&F, or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Republic Airlines, Inc.

Aircraft Public Water System Identification Number: AC0001860

FAA Registry Number: N34NG

Docket Number: 1300019

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format. Pursuant to 40 C.F.R. § 141.806, Republic Airlines, Inc. must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.

Based on EPA's review of ARCS, Republic Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0001860:

Complete and report the corrective actions required in response to a total coliform-positive sample. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). If any routine sample is total coliform-positive and *E.coli*-negative, the air carrier must perform corrective actions under 40 C.F.R. § 141.803(c)(3). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine D&F, or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Republic Airlines, Inc.

Aircraft Public Water System Identification Number: AC0001840

FAA Registry Number: N188WQ

Docket Number: 1300016

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format.

Based on EPA's review of ARCS, Republic Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0001840:

- Collect and report its routine coliform samples for calendar year 2012. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Routine coliform sampling is required under the ADWR per 40 C.F.R. § 141.803(b). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.
- 2. Perform and report the corrective actions required in response to the system's failure to collect required routine coliform samples in 2012 per 40 C.F.R. § 141.803(f). This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine disinfection and flushing (D&F), or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Republic Airlines, Inc.

Aircraft Public Water System Identification Number: AC0001859

FAA Registry Number: N339NG

Docket Number: 1300018

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format.

Based on EPA's review of ARCS, Republic Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0001859:

- Collect and report its routine coliform samples for calendar year 2012. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Routine coliform sampling is required under the ADWR per 40 C.F.R. § 141.803(b). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.
- 2. Perform and report the corrective actions required in response to the system's failure to collect required routine coliform samples in 2012 per 40 C.F.R. § 141.803(f). This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine disinfection and flushing (D&F), or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Republic Airlines, Inc.

Aircraft Public Water System Identification Number: AC0002243

FAA Registry Number: N127HQ

Docket-Number: 1300024

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format.

Based on EPA's review of ARCS, Republic Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0002243:

- Collect and report its routine coliform samples for calendar year 2012. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Routine coliform sampling is required under the ADWR per 40 C.F.R. § 141.803(b). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.
- 2. Perform and report the corrective actions required in response to the system's failure to collect required routine coliform samples in 2012 per 40 C.F.R. § 141.803(f). This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Pursuant to 40 C.F.R. §141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine disinfection and flushing (D&F), or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Republic Airlines, Inc.

Aircraft Public Water System Identification Number: AC0002249

FAA Registry Number: N133HQ

Docket Number: 1300025

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format.

Based on EPA's review of ARCS, Republic Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0002249:

- 1. Collect and report its routine coliform samples for calendar year 2012. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Routine coliform sampling is required under the ADWR per 40 C.F.R. § 141.803(b). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.
- 2. Perform and report the corrective actions required in response to the system's failure to collect required routine coliform samples in 2012 per 40 C.F.R. § 141.803(f). This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine disinfection and flushing (D&F), or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Republic Airlines, Inc.

Aircraft Public Water System Identification Number: AC0002258

FAA Registry Number: N164HQ

Docket Number: 1300027

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format.

Based on EPA's review of ARCS, Republic Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0002258:

- Collect and report its routine coliform samples for calendar year 2012. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Routine coliform sampling is required under the ADWR per 40 C.F.R. § 141.803(b). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.
- 2. Perform and report the corrective actions required in response to the system's failure to collect required routine coliform samples in 2012 per 40 C.F.R. § 141.803(f). This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine disinfection and flushing (D&F), or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Republic Airlines, Inc.

Aircraft Public Water System Identification Number: AC0002282

FAA Registry Number: N813MA

Docket Number: 1300028

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format.

Based on EPA's review of ARCS, Republic Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0002282:

- Collect and report its routine coliform samples for calendar year 2012. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Routine coliform sampling is required under the ADWR per 40 C.F.R. § 141.803(b). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.
- 2. Perform and report the corrective actions required in response to the system's failure to collect required routine coliform samples in 2012 per 40 C.F.R. § 141.803(f). This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine disinfection and flushing (D&F), or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Republic Airlines, Inc.

Aircraft Public Water System Identification Number: AC0002288

FAA Registry Number: N819MD

Docket Number: 1300029

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format.

Based on EPA's review of ARCS, Republic Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0002288:

- Collect and report its routine coliform samples for calendar year 2012. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Routine coliform sampling is required under the ADWR per 40 C.F.R. § 141.803(b). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.
- 2. Perform and report the corrective actions required in response to the system's failure to collect required routine coliform samples in 2012 per 40 C.F.R. § 141.803(f). This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine disinfection and flushing (D&F), or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Republic Airlines, Inc.

Aircraft Public Water System Identification Number: AC0002297

FAA Registry Number: N829MD

Docket Number: 1300030

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format.

Based on EPA's review of ARCS, Republic Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0002297:

- Collect and report its routine coliform samples for calendar year 2012. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Routine coliform sampling is required under the ADWR per 40 C.F.R. § 141.803(b). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.
- 2. Perform and report the corrective actions required in response to the system's failure to collect required routine coliform samples in 2012 per 40 C.F.R. § 141.803(f). This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine disinfection and flushing (D&F), or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Republic Airlines, Inc.

Aircraft Public Water System Identification Number: AC0001854

FAA Registry Number: N328NG

Docket Number: 1300017

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format. Pursuant to 40 C.F.R. § 141.806, Republic Airlines, Inc. must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.

Based on EPA's review of ARCS, Republic Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0001854:

- Perform and report its routine disinfection and flushing (D&F) during the third quarter of
  calendar year 2012. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d).
  Routine disinfection and flushing is required under the ADWR per 40 C.F.R.
  § 141.803(b). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA
  routine D&F events no later than 10 calendar days following the D&F period in which
  the D&F occurred.
- 2. Perform and report the corrective actions required in response to the system's failure to perform its routine D&F during the third quarter of calendar year 2012 per 40 C.F.R. § 141.803(f). This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine D&F, or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Republic Airlines, Inc.

Aircraft Public Water System Identification Number: AC0002257

FAA Registry Number: N163HQ

Docket Number: 1300026

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format. Pursuant to 40 C.F.R. § 141.806, Republic Airlines, Inc. must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.

Based on EPA's review of ARCS, Republic Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0002257:

- Perform and report its routine disinfection and flushing (D&F) during the third quarter of
  calendar year 2012. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d).
  Routine disinfection and flushing is required under the ADWR per 40 C.F.R.
  § 141.803(b). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA
  routine D&F events no later than 10 calendar days following the D&F period in which
  the D&F occurred.
- 2. Perform and report the corrective actions required in response to the system's failure to perform its routine D&F during the third quarter of calendar year 2012 per 40 C.F.R. § 141.803(f). This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine D&F, or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Republic Airlines, Inc.

Aircraft Public Water System Identification Number: AC0002259

FAA Registry Number: N165HQ

Docket Number: 1300035

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format. Pursuant to 40 C.F.R. § 141.806, Republic Airlines, Inc. must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.

Based on EPA's review of ARCS, Republic Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0002259:

- Perform and report its routine disinfection and flushing (D&F) during the third quarter of
  calendar year 2012. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d).
  Routine disinfection and flushing is required under the ADWR per 40 C.F.R.
  § 141.803(b). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA
  routine D&F events no later than 10 calendar days following the D&F period in which
  the D&F occurred.
- 2. Perform and report the corrective actions required in response to the system's failure to perform its routine D&F during the third quarter of calendar year 2012 per 40 C.F.R. § 141.803(f). This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine D&F, or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Republic Airlines, Inc.

Aircraft Public Water System Identification Number: AC0001839

FAA Registry Number: N187WQ

Docket Number: 1300014

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format. Pursuant to 40 C.F.R. § 141.806, Republic Airlines, Inc. must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.

Based on EPA's review of ARCS, Republic Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0001839:

- Perform and report its routine disinfection and flushing (D&F) during the fourth quarter
  of calendar year 2012. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d).
  Routine disinfection and flushing is required under the ADWR per 40 C.F.R.
  § 141.803(b). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA
  routine D&F events no later than 10 calendar days following the D&F period in which
  the D&F occurred.
- 2. Perform and report the corrective actions required in response to the system's failure to perform its routine D&F during the fourth quarter of calendar year 2012 per 40 C.F.R. § 141.803(f). This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine D&F, or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Republic Airlines, Inc.

Aircraft Public Water System Identification Number: AC0002261

FAA Registry Number: N167HQ

Docket Number: 1300031

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format.

Based on EPA's review of ARCS, Republic Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0002261:

- Collect and report its routine coliform samples for calendar year 2012. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Routine coliform sampling is required under the ADWR per 40 C.F.R. § 141.803(b). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.
- 2. Perform and report the corrective actions required in response to the system's failure to collect required routine coliform samples in 2012 per 40 C.F.R. § 141.803(f). This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine disinfection and flushing (D&F), or non-routine sampling within 10 days of the event.
- 3. Perform and report its routine disinfection and flushing (D&F) during the third quarter of calendar year 2012. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Routine disinfection and flushing is required under the ADWR per 40 C.F.R. § 141.803(b). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA routine D&F events no later than 10 calendar days following the D&F period in which the D&F occurred.
- 4. Perform and report the corrective actions required in response to the system's failure to perform its routine D&F during the third quarter of calendar year 2012 per 40 C.F.R. § 141.803(f). This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine D&F, or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.

Republic Airlines, Inc.

Aircraft Public Water System Identification Number: AC0005511

FAA Registry Number: N502LX

Docket Number: 1300032

The U.S. Environmental Protection Agency (EPA) oversees implementation of the Safe Drinking Water Act (SDWA), 42 U.S.C. §§ 300f - 300j-26, and the Aircraft Drinking Water Rule (ADWR), 40 C.F.R. §§ 141.800 – 810. To facilitate implementation of the ADWR, EPA has developed a centralized, web-based Aircraft Reporting and Compliance System (ARCS) for air carriers to use as an Agency approved method to submit required information in an electronic format.

Based on EPA's review of ARCS, Republic Airlines, Inc. is in violation of the SDWA and the ADWR by failing to do the following for public water system identification number AC0005511:

- Collect and report its routine coliform samples for calendar year 2012. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Routine coliform sampling is required under the ADWR per 40 C.F.R. § 141.803(b). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all sampling results no later than 10 calendar days following the monitoring period in which the sampling occurred.
- 2. Perform and report the corrective actions required in response to the system's failure to collect required routine coliform samples in 2012 per 40 C.F.R. § 141.803(f). This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine disinfection and flushing (D&F), or non-routine sampling within 10 days of the event.
- 3. Perform and report its routine disinfection and flushing (D&F) during the third quarter of calendar year 2012. This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Routine disinfection and flushing is required under the ADWR per 40 C.F.R. § 141.803(b). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA routine D&F events no later than 10 calendar days following the D&F period in which the D&F occurred.
- 4. Perform and report the corrective actions required in response to the system's failure to perform its routine D&F during the third quarter of calendar year 2012 per 40 C.F.R. § 141.803(f). This is a violation under 40 C.F.R. §§ 141.810(a) and 141.810(d). Pursuant to 40 C.F.R. § 141.806, air carriers must report to the EPA all events requiring notification to passengers or crew, or non-routine D&F, or non-routine sampling within 10 days of the event.

SDWA Section 1414, 42 U.S.C. § 300g-3, authorizes EPA to take formal enforcement action against public water systems for violations of the national primary drinking water regulations, including ADWR. With this notice of violation, Republic Airways Holdings is being offered the opportunity to meet with EPA at its regional office in Chicago, or via teleconference, to discuss the ADWR issues identified above. This letter is a notice of violation and informal request for information. It does not represent the initiation of a formal enforcement action.